Converted to a PDF without appended large-scale maps, Available at Balance Hydrologics, Inc. 800 Bancroft, Berkeley, CA 94710 (510) 704-1000

GROUNDWATER INVESTIGATION

DENNISTON CREEK VICINITY SAN MATEO COUNTY, CALIFORNIA

 For Coastside County Water District Half Moon Bay, California

Lowney-Kaldveer Associates**

Foundation / Soil / Geological Engineers

JOHN V. LOWNEY, C.E.
PETER KALDVEER, C.E.
ROBERT R. PRATER, C.E.
DONALD H. HILLEBRANDT, C.E.

145 ADDISON AVENUE, PALO ALTO, CALIFORNIA 94301

415/328-6920

April 4, 1974 349-2, PA 6644

Honorable Board of Directors Coastside County Water District 766 Main Street Half Moon Bay, California

Attention: Mr. Jack Canadas, Manager

RE: GROUNDWATER INVESTIGATION
DENNISTON CREEK VICINITY
SAN MATEO COUNTY, CALIFORNIA

Gentlemen:

In accordance with your request, we have performed a groundwater investigation for the above project. The accompanying report presents the results of our field investigation work, laboratory tests, and geological analyses. The basin hydrogeology and hydrology are discussed and recommendations for safe well yield and water resource management are presented.

We refer you to the text of the report for detailed recommendations. If you have any questions concerning our findings, please call.

Very truly yours,

LOWNEY/KALDVEER ASSOCIATES

JVL/MC:gs

Copies: Addressee (20)

TABLE OF CONTENTS

	Page No.
Letter of Transmittal	
TITLE PAGE	
TABLE OF CONTENTS	
INTRODUCTION	1
SCOPE	1
INVESTIGATION A. Subsurface B. Pumping Test	2 2 2
GEOLOGY	3
HYDROLOGY Surface Water Groundwater: Occurrence and Movement Specific Yield, Transmissibility, and Storage Capacity Table A – Values of Specific Yield for Denniston Creek Basin Table B – Basin Storage Capacity	4 4 4 5 6
HYDROLOGIC INVENTORY General Table C - Hydrologic Inventory	7 7 8
CONCLUSIONS – AVAILABLE WATER SUPPLY General Additional Well Development	9 9 9
RECOMMENDATIONS	11
FIGURE 1 - Boring Location Plan and Geologic Map	
FIGURE 2 – Groundwater Contours March 1974 Showing Elevation of Water Table	
FIGURE 3 - Geologic Section A - A'	
FIGURE 4 - Geologic Section B - B'	
FIGURE 5 - Geologic Section C - C'	
FIGURE 6 - Geologic Section D - D'	
APPENDIX A - FIELD INVESTIGATION Figure A-1, Key to Exploratory Boring Logs Exploratory Boring Logs Figure A-2, Pumping Test - (Drawdown vs. Time) Figure A-3, Pumping Test - (Recovery vs. Time)	A - 1

TABLE OF CONTENTS (Continued)

	Page No.
APPENDIX B - LABORATORY TESTING Figure B-1, Gradation Test Data Figure B-2, Gradation Test Data	B - 1
APPENDIX C - EXPLANATION OF HYDROLOGIC INVENTORY FACTORS	C - 1

DENNISTON CREEK AREA GROUNDWATER INVESTIGATION SAN MATEO COUNTY, CALIFORNIA

INTRODUCTION

In this report, we present the results of our groundwater investigation for the Denniston Creek and San Vicente areas located north of Half Moon Bay. The purpose of our study was to evaluate the potential for future subsurface water development within areas under the jurisdiction of the Coastside County Water District as a basis for management of the basin. The limits of our study are shown on the Boring Location Plan and Geologic Map, Figure 1, and approximately encompass the terrain bounded by the communities of El Granada on the south, Moss Beach on the north, the coast hills on the east, and the Pacific Ocean. In general, our study limits include the flatland discharge basins for San Vicente and Denniston Creeks from their emergence in the hills to discharge into the Pacific Ocean and Half Moon Bay, respectively.

We understand that it is desired to increase the existing plant capacity by means of additional wells and/or enlarged diversions of surface water from Denniston and San Vicente Creeks. At the present time, the District is extracting approximately 400 acre feet annually from Denniston Creek. This water is pumped to a water treatment plant situated on Denniston Creek and then transported by 12-inch line for distribution in the Half Moon Bay area.

Recognition is given to Jeremy C. Wire, Engineering Geologist, for assistance in preparing the hydrogeologic and hydrologic sections of the report.

SCOPE

The scope of our work consisted of the following:

- Review of available hydrology and subsurface data including well logs, private and public reports, and technical data obtained from interviews with knowledgeable personnel of the U. S. Geological Survey, San Mateo County, the Coastside County Water District, Citizens Utility Water District, and others.
- 2. Limited field geologic mapping to supplement recent detailed mapping performed by the U. S. Geological Survey. Aerial photographs were reviewed by our engineering geologist, who also performed magnetometer traverses to locate a concealed fault east of Highway 1.
- 3. An extensive subsurface exploration program to define the subsurface materials, groundwater table, and bedrock depth.

- 4. A field pumping test to determine the aquifer transmissibility and recovery characteristics for well spacing determination, etc.
- 5. Preparation of a large scale geologic map for the basin, geologic cross-sections, and determination of present water quality from available chemical test data, as well as contour maps showing water table elevations and bedrock surface elevations. Analyses of hydrogeology, hydrologic inflow outflow for the basin, and conclusions and recommendations for water resource management.

INVESTIGATION

A. Subsurface

A subsurface investigation was performed between January 25 and February 27, 1974, using truck-mounted rotary wash equipment. Eleven borings ranging from 35 to 140 feet in depth were drilled at the locations shown on Figure 1. All borings were backfilled with pea gravel; at least 20 feet of perforated P.V.C. pipe was installed at the surface of each boring for long-term monitoring of the water table elevations. Logs of the borings showing materials encountered, sampling intervals, and drilling rates are presented in Appendix A, as well as an explanatory key describing the soil classification system used. The results of laboratory classification tests are presented in Appendix B.

B. Pumping Test

Since limited data from specific-capacity tests and well logs were available for the study area, one aquifer or pumping test was made using the District's Denniston Creek Test Well No. I to determine aquifer properties, with particular respect to transmissibility. The coefficient of transmissibility (T) indicates the capacity of the aquifer system as a whole to transmit water and is equal to the coefficient of field permeability multiplied by the total saturated thickness of the aquifer.

As shown in Appendix A, which contains the pumping test results, measurements of drawdown and recovery were made in both the pumped well and in an observation well (Exploratory Boring 1) for a period slightly in excess of 48 hours. The analysis of the aquifer coefficients was made using a modification of the Theis non-equilibrium equation. When plotted on semi-logarithmic paper, the drawdown curve approaches a straight line when sufficient time has elapsed after pumping beings. Transmissibility (T) in gallons per day per foot is then determined from the relationship T = 264Q,

where Q is the pumping rate in gallons per minute and ΔS is the change in drawdown in feet per log cycle in the straight line portion of the drawdown curve.

Reasonable agreement was obtained when computing the coefficient of transmissibility from both the drawdown and recovery data. A value of 13,600 gallons per day per foot was obtained based on the drawdown measurements, and a corresponding value of 16,500 gallons per day per foot was obtained using the recovery measurements. For purposes of evaluation of the groundwater hydrology and the groundwater basin inventory, an average of these two values, or a coefficient of transmissibility (T) of 15,000 gallons per day per foot, is used.

GEOLOGY

The general geology of the area with respect to structural features controlling ground-water movement is shown on the Geologic Map, Figure 1, and the Geologic Sections presented on Figures 3 through 6. The geologic setting has been largely affected by faulting. Approximately 150 feet of vertical uplift of the Seal Cove Fault has created a ridge of impermeable Tertiary Age Purisima Formation siltstone along the west margin of both the Denniston Creek and San Vicente Creek Basins. A parallel fault has been mapped by the U.S.G.S., and was detected and field located during the magnetometer traverses about 800 feet east of Highway 1 near the existing District wells. This fault does not appear to interfere with groundwater movement, based on the water table contouring and the aquifer pumping test.

Basement rocks for this region consist of relatively impermeable granite, which constitutes the highlands to the east and is overlain over most of the basin by Purisima siltstone. Several stages of marine terraces blanket the bedrock units; these terraces have been elevated several hundred feet by faulting, forming the aquifers for groundwater storage under study. In places, recent stream wash and basin alluvial deposits formed primarily by the creeks occur as a surficial mantle over the terraces.

The significant aquifer materials consist of unconsolidated silty sands, clayey sands, and coarse to fine sands separated over most areas by an intermediate sandy clay stratum up to 20 feet thick (see Figures 3 - 6). The deepest portion of the basin consists of silty sand and coarse to fine sand; this primary water bearing unit increases in thickness toward the east above Highway 1 to a maximum thickness of approximately 55 feet. A bedrock ridge, possibly caused by traverse faulting normal to the regional northwest fault trend, was found to exist north of the airport where the valley narrows. The bedrock surface in this latter area rises to Elev. 20. Bedrock surface contours from wells and the test borings, as shown on Figure 1, indicate that within the Denniston Creek Basin the basement surface through the basin center is relatively flat at approximately Elev. -30 sloping upward at the margin of the valley. Block tilting or warping has created a gentle bedrock gradient southward toward Half Moon Bay of 10 to 15 feet per mile through the center of the valley.

HYDROLOGY

Although groundwater is stored in the water bearing deposits of the basin, the ultimate availability is determined by recharge and discharge to the groundwater reservoir including the amount of rainfall, streamflow, and types and areas of natural discharge or artificial discharge through wells. Therefore, as a pre-requisite to constructing a hydrologic balance or inventory for the groundwater basin in order to estimate the available supply, we have attempted to obtain as much reliable data as possible on both surface and groundwater conditions for the area.

Surface Water

Average annual rainfall in the vicinity of the study area varies from approximately 20 inches in the lowland area near Princeton to nearly 45 inches in the higher portions of the watershed area of San Vicente and Denniston Creeks on Montara Mountain. Since rainfall is the ultimate source of recharge to the groundwater basin, a large amount of water is potentially available for yearly replenishment. Estimates made by the University of California, Agricultural Extension Service, indicate that the watershed of San Vicente Creek covers some 1209 acres, with elevations up to 2000 feet, collecting an average annual rainfall of 4095 acre feet. Similarly, the watershed of Denniston Creek to an elevation of 2000 feet covers some 2636 acres, collecting an average annual volume of rainfall amounting to some 9203 acre feet.

Periods of surface water runoff mainly occur in the period of October through March as a result of winter storms. At the present time, there are no historic stream gauge records for San Vicente Creek, and stream gauge readings are available for Denniston Creek only during the period March, 1968, to December, 1970. Excluding base flow which is sustained by springs and diversions made by the Coastside County Water District from the two creeks, we have estimated that 80 percent of the rainfall of the watershed area of the two creeks may be available as runoff. This condition is substantiated by rainfall/runoff relationships of gaged basins having a similar geologic and topographic setting in adjacent portions of the Coast Range.

Groundwater: Occurrence and Movement

Measurements of water levels in observation wells situated in various portions of the basin made especially for this investigation indicate that at the present time (March, 1974) the basin is more or less brimfull with a water table gradient and configuration that approximates the land surface topography and elevation as shown on Figure 2, Water Level Contour Map. This map shows that there are two separate basins in the study area: the smaller basin in the vicinity of Moss Beach (herein designated as the San Vicente

Subarea) has a surface area of approximately 140 acres and is separated from the larger contiguous groundwater basin to the southeast by a low groundwater divide. The larger groundwater basin, which for purposes of reference is divided into the Denniston Creek and Airport Subareas delineated on Figure 2, covers approximately 879 acres.

With the possible exception of an area in the vicinity of Princeton near the Bay where thick clay sequences are present, groundwater in the overall area is believed to be mostly unconfined. It is, therefore, believed that the water table in the area will fluctuate primarily in response to changes in the amount of recharge by rainfall and streamflow; there are no historic well hydrographs in the immediate vicinity to substantiate this, however. With no data to indicate otherwise, the groundwater contours shown on Figure 2 are believed to represent not only the present configuration of the water table but also the historic steady state condition of minimal groundwater water development.

As shown on the groundwater contour map, Figure 2, the hydraulic gradient is generally to the south and southeast toward the Bay at some 50 to 70 feet per mile, extending from recharge areas concentrated along the northeast boundary of the basin to areas of effluent or discharging groundwater in a low lying marsh area west of Princeton. No groundwater is believed moving out of the consolidated rock of the ridge west of the Seal Cove Fault Zone, as the direction of flow is parallel to the fault zone. Although the presence of other surface and subsurface faults is suggested by geologic relationships, none of the faults appear to create a barrier to the water flow in either the Denniston Creek or the Airport Subareas.

Our review of existing water quality test records from wells within the basin indicates saline water encroachment has not occurred to date, although chlorides are higher than typically found in fresh water basins. Chloride concentrations range from approximately 60 to 110 parts per million; this may be the result of salt residue remaining from ancient times when the terraces were inundated by seawater.

Specific Yield, Transmissibility, and Storage Capacity

Physical parameters of the groundwater basin that will control the rate and amount of groundwater withdrawal possible under any future management plan are related to the specific yield, transmissibility, and storage capacity of the aquifer system. The derivation of the value for transmissibility was described previously under the explanation of the aquifer test program. Specific yield is defined as the ratio of (1) the volume of water which, after being saturated, will yield by gravity to (2) its own volume. Therefore, the amount of groundwater in storage (storage capacity) of the groundwater basin is equal to the total volume of saturated material multiplied by its specific yield.

For the purpose of computing storage capacity, the overall basin was divided into subareas, with emphasis on evaluating the Denniston Creek Subarea which is within the jurisdiction of the Coastside County Water District. These subareas were selected partly for convenience, but they also generally coincide with natural geologic and hydrologic boundaries. As determined from the logs of test wells, different types of subsurface water bearing materials were assigned various specific yield values as follows:

TABLE A - VALUES OF SPECIFIC YIELD FOR DENNISTON CREEK BASIN

Material	Percent
Gravel, medium and coarse grained sand	25
Fine sand	10
Clay	. 3
Bedrock (Purisima formation or granite)	10

Based on weighted averages of the percentages of various classifications of the material present in both shallow and deep wells, average specific yields were assigned to the subareas. The Denniston Creek Subarea has the highest average specific yield, approximately 13 percent; the Airport and San Vicente Subareas have average specific yields of approximately 11 percent. These relatively low values reflect the generally fine-grained nature of the deposits forming the aquifer system.

If the total saturated volume of the aquifer system to the top of bedrock as contoured on Figure 2 is considered, then approximate storage capacities for the various subareas are as follows, using the above specific yield values:

TABLE B - BASIN STORAGE CAPACITY

Subarea	Acre Feet
San Vicente	995
Denniston Creek	1800
Airport	4630
Total Storage Capacity	7425

If the storage computations are made on only the volume of the groundwater basin which is above sea level, however, the calculated storage capacity for the Denniston Creek and Airport Subareas would be reduced by approximately one-third because of the potential for sea water intrusion if groundwater levels decline below this elevation. Usable groundwater storage capacity under this criterion would be about 1200 acre feet for the Denniston Creek Subarea and approximately 3050 acre feet for the Airport Subarea.

HYDROLOGIC INVENTORY

General

Although from the performance of the existing wells and general knowledge of the area it would appear feasible to drill and complete several additional wells in the Denniston Creek area physically capable of yielding adequate quantities of water, the primary question to be answered by this investigation is: What will the practical sustained rate of groundwater pumping from the basin be? In other words, how much groundwater can be pumped year after year without serious decline of the water table resulting in mining or overdraft of the aquifer, causing water of inferior mineral quality to move into the basin, such as from a wedge of salt water intrusion, or reducing the surface flow of Denniston or San Vicente Creeks to the point where any water rights to such surface sources are impaired?

Accordingly, the purpose of collecting and evaluating the basic geologic and hydrologic data is to supply quantities to a hydrologic inventory or equation for the groundwater basin which states:

Inflow (streams, rainfall) - Outflow (streams, subsurface flow) = Consumptive use (pumping for water supply or irrigation, evaporation) \pm Change in the amount of groundwater storage

All water that enters the basin during a certain time period must be accounted for, and will either be stored, evaporated, pumped out, or will leave as surface or subsurface flow.

Under present conditions, as will be demonstrated in Table C, the hydrologic system is probably in balance, there is a minimal amount of pumping, and the amount of groundwater in storage is generally unchanging from year to year. Once increased pumpage occurs, however, any pumping in excess of the long-term amount of natural recharge will remove groundwater from storage and could lead to undesirable overdraft. The perennial yield, or the amount of water which can be pumped year after

year cannot exceed the long-term natural recharge to or discharge from the groundwater reservoir. As shown in Table C, Hydrologic Balance, the amount of additional water which can be pumped without removing groundwater from storage is roughly equivalent to the discharge that can be salvaged. In this case, this potentially salvageable water is represented by effluent groundwater which sustains the high-water table around Princeton and by surface runoff which is rejected as recharge and evaporates or wastes to Half Moon Bay by way of Denniston Creek. The effluent groundwater near Princeton is now being evaporated or consumed by native grasses and other phreatophytes.

Normally, a base period is selected for the hydrologic balance which is representative of long-term average conditions. In this case, however, no long-term base period data for surface water inflow or outflow or for quantities of pumpage are available. Since we believe that the groundwater basin is probably in a steady state condition, this lack of long-term average data may not be a serious problem. As shown in the explanatory notes in Appendix C for the hydrologic inventory that follows, the basic data in some cases are fragmentary, come from several sources, and in some cases must be considered simply as knowledgeable estimates.

TABLE C - HYDROLOGIC INVENTORY

Estimated Items of Water Supply and Disposal

Denniston Creek and Airport Subareas

(Average Yearly Basis)

INFLOW		ACRE FEET	• •
Streamflow Precipitation on Valley Floor Subsurface Inflow from San Vicente Subarea Subsurface Inflow from Consolidated on Margin of Basin		9600 1050 350	
	Total	11,000	•
OUTFLOW		•	
Stream flow to Half Moon Bay Consumptive use by natural vegetation phreatophytes Subsurface Outflow to Bay Pumpage for Irrigation Surface water exported from basin by Coastside County Water District Miscellaneous Pumpage (Domestic and Municipal)		7300 1250 1200 500 400	:
ז	otal	11,000	

Change in Groundwater Storage = 0

 ^{*} See Appendix C for explanation of quantities shown.

CONCLUSIONS - AVAILABLE WATER SUPPLY

General

With particular respect to the Denniston Creek Subarea, which is under the direct management of the Coastside County Water District, we can draw several conclusions pertaining to the groundwater storage capacity of the basin, the amount of groundwater which should be available on a long-term average basis, and on alternative schemes of using surface and groundwater water supply sources as would be required in the present and future management program for the Denniston Creek Subarea and the basin as a whole.

Based on the data that we have developed, it appears that the storage capacity of Denniston Creek and San Vicente Subareas of the basin is limited, particularly if only the volume of storage above mean sea level is considered. For the Denniston Creek Subarea, the maximum calculated storage capacity is 1800 acre feet, and the minimum value to mean sea level is approximately 1200 acre feet. In other words, these volumes of groundwater establish an absolute upper limit of groundwater potentially available from the Subarea if no recharge were to occur. In addition to the limited storage capacity, the ability to transmit groundwater from the point of recharge to the point of withdrawal by a well field, as evidenced by the coefficient of transmissibility is also limited. Therefore, the basin is not as responsive to short-term changes in the available recharge as it might be, due to the fine-grained and slowly withdrawn from storage by wells may take a long time to replace. The length of such a period is not known, since no historic well hydrographs indicating fluctuations of the water table over a period of time exist.

On the more positive side, as far as the threat of sea water intrusion is concerned, the slowly permeable nature of the aquifer system would not allow such a condition to develop rapidly. Much groundwater would have to be removed from storage with a subsequent considerable lowering of the hydraulic gradient before the wedge of saline water would move a significant distance onshore.

Additional Well Development

Based on our evaluation of hydrologic and geologic subsurface conditions as well as the hydrologic inventory for the area, it is our opinion that an additional 400 acre feet per year could be withdrawn by properly spaced wells in the Denniston Creek and Airport Subarea, without significantly reducing the hydraulic gradient or removing

significant amounts of groundwater from storage. The most likely effect of such development would be to induce additional recharge from Denniston Creek and other surface sources, so that less annual surface water flow would waste to the Bay. As the groundwater basin adjusts to a new equilibrium condition, and this might take many years, some lowering of the water table in the area of effluent groundwater flow in the vicinity of Princeton would occur and this land could be more beneficially used.

If additional groundwater extractions as large as 800 acre feet per year are made, some lowering of the water table gradient to the range of 30 to 35 feet per mile should be expected. Additionally, substantial lowering of the water table in the effluent area near Princeton would result, inducing a change in vegetation types from the existing marsh grass types. Although we do not at this time foresee sea water encroachment as the result of withdrawals on the order of 800 acre feet per year maximum, since a positive seaward water table gradient would still be maintained, the long-term effects of such pumpage are difficult to predict and it may be necessary to reduce this 800 acre foot upper limit if combined pumpage and stream diversion lead to overdraft conditions. It is be installed in stages, with an evaluation period between stages to determine effects on the water table over several seasons.

Pumpage can be done on a seasonal basis with recharge during the wet season, provided regional surveillance of the water table indicates no long-term lowering effect. Thus, for instance, 8 wells pumping 60 to 75 gallons per minute for 6 months are feasible, as they would result in a net withdrawal of 400 acre feet per year. Proper well location and spacing would be important in this case. Figure 1 shows general locations for 8 additional wells.

In addition to the above new well development, the 500 acre feet of water currently withdrawn for farming, as shown in Table C, can be used for future District supplies if development replaces farming in the Denniston Creek basin.

Any plan to develop additional groundwater supplies over and above the 400 acre feet per year quantity should also consider conjunctive use of both surface and groundwater resources. In other words, the perennial yield and physical limitations of storage and transmissibility of the aquifer system may limit the flexibility of using the groundwater resource entirely. There is no imminent danger in over-development and removing groundwater from storage and exceeding the perennial yield for a period of several years, if it is realized that groundwater removed from storage eventually must be replaced to assure that undesirable conditions such as sea water intrusion do not occur. Groundwater reservoirs can be utilized similar to a surface water reservoir -- drawndown and replenished -- but the limitations must be realized in any management scheme. This is particularly true of the basin investigated where the transmissibility is low and the time to replace significant quantities of groundwater removed from storage may be great.

We have considered the use of the existing District test wells for recharge of surplus surface water to the groundwater basin. However, the low aquifer transmissibility makes this method unfeasible, in our opinion.

RECOMMENDATIONS

Based on the foregoing conclusions, we recommend that the District consider the following in a management plan to develop additional short-term and long-term water supplies for the Denniston Creek and San Vicente Subareas and adjacent portions of the groundwater basin.

- 1. As noted, an additional 400 acre feet per year (six to eight wells pumping 60 to 75 gallons per minute for six months per year) can be extracted from the Denniston Creek and Airport Subareas to meet immediate future needs without affecting the hydrologic balance or inviting sea water intrusion. These wells should be spaced out over the portion of the basin, where the aquifer is thickest, as shown on Figure 1. One of the District's three existing test wells on Denniston Creek should be pumped, also, as part of the additional groundwater extraction. Wells should be drilled to bedrock elevation as shown on the Bedrock Contour Map (Figure 1) and should be spaced a minimum distance of 400 feet to minimize interference. Additional wells, pumping up to a maximum total of 800 acre feet per year, are likely feasible, providing surveillance of coastal water quality and overall basin water table conditions is initiated. The water quality surveillance should consist of three or four perimeter monitoring wells along Half Moon Bay in which periodic chloride concentration determinations can be made.
- 2. Storage capacity of the San Vicente Subarea is small and no further development by wells is recommended in this area. This subarea is in a critical position, because subsurface recharge from San Vicente Creek passes through it into the Airport Subarea. Any significant reduction of the groundwater in storage in the San Vicente Subarea would reduce proportionately the underflow to the adjacent basin.
- 3. As part of a management program, in order to obtain the best conjunctive use of surface and groundwater, the possibility of further diversion of surface flows of San Vicente Creek and Denniston Creek should be evaluated. Since surface flow is and will continue to be rejected by the groundwater basin even under conditions of further well development, it may be possible to divert such flow upstream from the basin through one or more small dams

or infiltration galleries installed in the alluvial materials of the stream bed. Upstream diversions utilizing surplus stream runoff would not affect the construction of the proposed wells.

As a planning yardstick, surface water diverted from Denniston Creek may be substituted for groundwater pumpage on a 4:1 ratio, within the maximum constraints previously discussed. In other words, 4 acre feet of surface water can be taken for each acre foot of subsurface water to have an expected equivalent affect on the groundwater basin. This makes surface diversion highly efficient compared to subsurface withdrawal.

4. Long-term basic water resource data for the area are needed if the basin is to be managed to its full potential. The hydrologic balance presented with this report is only an attempt at providing an insight into the items of water supply and disposal. To accurately assess the effect of any basin operation scheme over a long or short term period, permanent stream gauges on San Vicente and Denniston Creeks should be established. Periodic seasonal measurements on groundwater levels in observation wells established in this investigation should be made, to monitor any changes in groundwater storage. Finally, as more basic data becomes available on elements of the hydrologic equation, a mathematical model of the basin should be constructed to provide a working tool in assessing the effects of various basin operation schemes on the behavior of the ground and surface water regimen.

APPENDIX A - FIELD INVESTIGATION

The field investigation consisted of a surface reconnaissance for geologic mapping and well inventory purposes, and a subsurface exploration program using a truck-mounted rotary wash drill rig. Eleven exploratory borings were drilled within the Denniston Creek and San Vicente Creek basins between January 25th and February 27th, 1974. The locations of the exploratory borings, which extended to a maximum depth of 140.0 feet, are shown on the Boring Location Plan, Figure 1. The soils encountered in the borings were continuously logged in the field by our representative and described in accordance with the Unified Soil Classification System ASTMD-2487. The logs of the borings as well as the key for the classification of this soil are included as part of this appendix.

Representative soil samples were obtained from the exploratory borings at selected depths appropriate to the soil investigation. All samples were returned to our laboratory for classification and testing.

Standard penetration resistance blow counts were obtained by dropping a 140 pound hammer through a 30 inch free fall. The 2 inch O.D. split spoon sampler was driven 18 inches and the number of blows recorded per each 6 inch penetration or for any penetration less than 6 inches if high resistance was encountered. Undisturbed samples of the bedrock material were recovered in a thin wall Shelby tube using the pitcher barrel sampler. The type of sampler used to obtain the samples is symbolized below and is designated on the boring logs at the appropriate sample depths.

Standard Split Spoon Sampler

-Pitcher Barrel Sampler

The upper 20 feet of all borings was cased with 2 inch diameter p.v.c. piezometer pipe, except Boring 1 in which 120 feet of casing was used. The piezometers were backfilled with pea gravel and left in place for future monitoring of groundwater levels and water quality.

Boring logs show our interpretation of the subsurface conditions on the dates and at the locations indicated; it is not warranted that they are representative of subsurface conditions at other locations and times. Also the stratification lines of the logs represent the approximate boundary between soil types and the transition may be gradual.

Boring elevations were taken from the County of San Mateo topographic base map having 10 feet contour intervals.

Field magnetometer traverses were performed across the fault located approximately 1,000 feet east of Highway 1.

Field pumping test was performed in the District's Well No. I located on Denniston Creek to determine the aquifer permeability and safe yield. Exploratory Boring I served as an observation well for this test. Details of the methods used and results have been presented in the report. Drawdown and recovery data from this test are presented in this appendix.

	Р	RIMARY DIVISION	NS		
	7.	GRAVELS	CLEAN GRAVELS	GW	Well graded gravels, gravel-sand mixtures, little or no fines.
	SOILS MATERIAL 3. 200	MORE THAN HALF OF COARSE	(LESS THAN 5% FINES)	GP	Poorly graded gravels or gravel-sand mixtures, little or no fines.
		FRACTION IS LARGER THAN	GRAVEL	GM	Silty gravels, gravel-sand-silt mixtures, non-plastic fines.
	INE F O IAN SIZI	NO. 4 SIEVE	FINES	GC	Clayey gravels, gravel-sand-clay mixtures, plastic fines.
		SANDS	CLEAN SANDS	sw	Well graded sands, gravelly sands, little or no fines.
	COARSE G	MORE THAN HALF OF COARSE	(LESS THAN 5% FINES)	AVEL GM Si	Poorly graded sands or gravelly sands, little or no fines.
	CO/ ORE IS L	III EDACTION IC	SANDS WITH	SM	Silty sands, sand-silt mixtures, non-plastic fines.
	Σ		FINES	sc	Clayey sands, sand-clay mixtures, plastic fines.
	ILS OF LER SIZE	SILTS AND	CLAYS ·	ML	Inorganic silts and very fine sands, rock flour, silty or clayey fine sands or clayey silts with slight plasticity.
	ED SOILS HALF OF SMALLER SIEVE SIZ	LIQUID LIM		GP Poorly graded gravels or gravel-sand mixtures, litter no fines. GM Silty gravels, gravel-sand-silt mixtures, non-plastic GC Clayey gravels, gravel-sand-clay mixtures, plastic SW Well graded sands, gravelly sands, little or no fine SP Poorly graded sands or gravelly sands, little or no SM Silty sands, sand-silt mixtures, non-plastic fines. SC Clayey sands, sand-clay mixtures, plastic fines. ML Inorganic silts and very fine sands, rock flour, silty clayey fine sands or clayey silts with slight plastic flays, sandy clays, silty clays, lean clays. OL Organic silts and organic silty clays of low plasticity. MH Inorganic silts, micaceous or diatomaceous fine sand silty soils, elastic silts. CH Inorganic clays of high plasticity, fat clays. OH Organic clays of medium to high plasticity, organic	Inorganic clays of low to medium plasticity, gravelly clays, sandy clays, silty clays, lean clays.
	INED AN HAIS IS SI	LESS THAN	1 50%	OL	Organic silts and organic silty clays of low plasticity.
	a O	SILTS AND	CLAYS	МН	Inorganic silts, micaceous or diatomaceous fine sandy or silty soils, elastic silts.
	FINE GRA. MORE TH. MATERIAL THAN NO. 2	LIQUID LIMIT IS		СН	
L	正元其	GREATER THA	N 50%	AYS MH Inorganic sil silty soil: S CH Inorganic cla	Organic clays of medium to high plasticity, organic silts.
L	HIC	GHLY ORGANIC SOILS	3	Pt	Peat and other highly organic soils.

DEFINITION OF TERMS

2	200	U.S. STANDARE 40	SERIES 10	SIEVE			E SIEVE OPE	NINGS
SILTS AND CLAYS		SA	ND		GR/	WEL		
7.11.0 02.110	FINE	E MEC	MUIG	COARSE	FINE	COARSE	COBBLES	BOULDERS

GRAIN SIZES

	SANDS,GRAVELS AND NON-PLASTIC SILTS	
	VERY LOOSE LOOSE MEDIUM DENSE DENSE VERY DENSE	0 - 4 4 - 10 10 - 30 30 - 50 OVER 50
ı		•

CLAYS AND PLASTIC SILTS	STRENGTH [‡]	BLOWS/FOOT †
VERY SOFT SOFT FIRM STIFF VERY STIFF HARD	0 - 1/4 1/4 - 1/2 1/2 - 1 1 - 2 2 - 4 OVER 4	0 - 2 2 - 4 4 - 8 8 - 16 16 - 32 OVER 32

RELATIVE DENSITY

CONSISTENCY

Number of blows of 140 pound hammer falling 30 inches to drive a 2 inch O.D. (1-3/8 inch I.D.)

split spoon (ASTM D-1586).

†Unconfined compressive strength in tons/sq. ft. as determined by laboratory testing or approximated by the standard penetration test (ASTM D-1586), pocket penetrometer, torvane, or visual observation.

Lowney-Maldveer Associates

KEY TO EXPLORATORY BORING LOGS Unified Soil Classification System (ASTM D-2487)

Foundation / Soil / Geological Engineers

denniston creek groundwater investigatio. HALF MOON BAY, CALIFORNIA

PROJECT NO. DATE 349-2 March, 1974

Figure A-1

DRILL RIG Rotary Wash		SURFACE	ELEVATION	50	feet		LOGGE	D BY	R.D.R.	
DEPTH TO GROUNDWATER 10.5 feet		BORING D	IAMETER	5 in	ches		DATE D	RILLED		
DESCRIPTION AND CLASS	SIFIC	ATION			DEPTH	LER	RATION FANCE S/FT.)	TER NT (CL)	Bů +	SSIVE
DESCRIPTION AND REMARKS .	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (C.	Drilling Rate min/ft	UNCONFINE COMPRESSIV STRENGTH
SANDY CLAY		dark brown to black	firm	CL	- 1				*	
·		gray~ brown			- 4					
SILTY SAND, with lenses of red- brown silt, (decomposed granite sands)		yellow- brown	medium dense	SM	- 8 - - 9 - - 10		 -	3/18/7	74	t
Percent Passing #200 Sieve = 58					11 - 12 - 13 - 14 - 15 - 16 - 17 - 17 - 17		16	23		
* Drilling rate faster than 1/4 min/ft from 0 to 35 feet				- - - -	18 -					
Construction 15 and 15	· · · · · · · · · · · · · · · · · · ·		EXPLO	DRAT	ORY E	30F	RING	LOG		
Foundation / Soil / Geological Engineers			ISTON CR HALF MO JECT NO.	NOC	GROUN BAY, (DATE -il, 197	CAL	JFOR BOI	RINV NIA RING NO.	ESTIGA	TIC)

3

中學

\$ 15 to

DRILL RIG Rotary Wash			ELEVATION	50 f	eet	_	LOGGE	DBA	R.D.R	
DEPTH TO GROUNDWATER 10.5 feet		BORING D	IAMETER &	incl	nes	<u>_</u>	DATE D		1/25/	74
DESCRIPTION AND CLASS	SIFIC	CATION		·	DEPTH	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	5 .+-	FINED ESSIVE MGTH
DESCRIPTION AND RÉMARKS	SYM BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SA.	PENET RESIS (BLOV	CONTE	Drilling Rate min/ft	COMPRESSIVE STRENGTH
SILTY SAND, (continued)		yellow- brown	medium dense	SM	21 -		27	14		
·					- 23 - - 24 - - 25 - - 26 - - 27 -					
(grading clayey at 30.0 feet)		gray– brown	dense		- 28 - - 29 - - 30 - - 31 - - 32 - - 33 -		30			ı
(less clay at 35.0 feet)		red- brown			- 34 35 37 38 39 39				.25 .25 .25	
SANDY CLAY		green- gray	very stiff	CL	- 40 -				.25	
LOUNCY-Haidvaar Associates Foundation / Soil / Geological Engineers			NISTON (H/	CREEK	TORY E GROU AOON E DATE pril, 197	N(DWATI Y, CA	ER IN	VESTIC	YATIC

DRILL RIG Rotary Wash		SURFACE	ELEVATION	50	feet	LOGG	ED BY	R.D	R
DEPTH TO GROUNDWATER 10.5 feet		BORING DI	AMETER	6 inc	hes	DATE	DRILLET	1/25,	
DESCRIPTION AND CLA	SSIFIC	CATION				TION NOE (FT.)	[3]		
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER PENETRATION RESISTANCE (GLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UMCONFINED COMPRESSIVE
with lenses of fine grained silty and at 54.0 feet)	1	green- gray	very		- 41 42 43 44 45 46 48 49 50 - 51 - 52 - 53 - 54 - 55 - 56 - 57 - 58 - 59 - 50 - 50 - 50 - 50 - 50 - 50 - 50	38/4"		.30 .50 .75 .50	
LOUITES - LEGINGER POSITIONS Foundation / Soil / Geological Engineers		dennis	EXPLO TON CRE HALF 1	EK G		WATER	INIVE	STIGAT	llo /
gival Engineers		PROJE	CT NO.		DATE	BOR			
	1	349-	2		, 1974	NO			

DRILL RIG Rotary Wash		SURFACE	ELEVATION	50	feet		LOGGEI	D BY	R.D.R	and the second second second
DEPTH TO GROUNDWATER 10.5 feet		BORING D	AMETER		iches		DATE D	RILLED		
DESCRIPTION AND CLASS	SIFIC	ATION		·	DEPTH	'LER	TANCE S/FT.)	TER NT (%)	ing ft	FINED ISSIVE IGTH
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	1 1	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONFINED COMPRESSIVE STRENGTH (KSF)
SANDY CLAY, (continued)		blue- gray	very stiff	CL	- 61 - - 62 -				.25	
SILTY SAND, fine, uniform		blue- gray	very dense	SP SM	63 - 64 - 65 - 65				.25	
					- 66 - - 67 - - 68 - - 69 -				.10 .10 .20	
					- 70 - 71 - 72 - 73				.10	
Percent Passing #200 Sieve = 12		-			74		90	 - -	.10	
SANDY SILTSTONE, with shells, fine uniform sand (Purisima Formation)		i	low hardness		79 – - 80 –				1.0	
Launey-Raisveer Responsibles Foundation / Soil / Geological Engineers		PRO	ISTON CI	REEK 100	GROUN N BAY, DATE	CA 1DV	VATER LIFO BO	RINV	'ESTIG	ATION

A

33

1. Sept. 1.

via Est

100

DRILL RIG Rotary Wash			ELEVATION	50 f	cet		LOGGE	DBY	R.D.R
DEPTH TO GROUNDWATER 10.5 feet		BORING DI	AMETER	6 inc	hes			RILLED	1/25/
DESCRIPTION AND CLAS	SSIFIC	ATION			DEPTH	E.B.	ATION ANCE /FT.)	ER T (° 3)	စ္
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (°3)	Drilling Rate min/ft
SANDY SILTSTONE, (cont)		dark	low		- 81 -				2.0
		gray	hardnes	s	 - 82 -				2.0
	:								2.0
					- 83 				2.0
					- 84 -				2.0
				F	- 85		4/6"	-	2.0
				F	86 -				2.0
				F	87 -				
				F	88				2.5
				F	89 -				2.0
				F	- 90-				1.5
				F	91 -				1.5
				F	92 -				1.5
				F	93 -				1.5
		·		F	94 -				
Percent Passing #200 Sieve=47				F	95	Γi		8	
Dry Density = 114 pcf				-	96-			° -	
				F	97	4			
				-	98 –				1.5
				-	99-			-	
					101_			-	1.5
F 1797 \$177 \$29 a From Soft part on the Ellips of the color of the col			EXPLO	RATO	DRY B	OR	ING L		
Louisy-Maiducer Associates		DENNIS	TON CRE	EK G	ROUN	DW	ATER	INVES	TIGATI
Foundation / Soil / Geological Engineers			CT NO.		DATE		BORI	NG	
		349-2		Ар	ril, 197	74	NC). 	1

DRILL RIG Rotary Wash			ELEVATION	50	feet		LOGGE	DBY	R.D.	D
DEPTH TO GROUNDWATER 10.5 feet		BORING D	IAMETER (inch	ies		DATE D	RILLED	1/25	
DESCRIPTION AND CLAS	SIFIC	CATION				Œ	NOT P	(3)		
DESCRIPTION AND REMARKS	SYM BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOW/S/FT.)	WATER CONTENT (%)	Drilling 1 Rate 1 min/it	UNCONFINED COMPRESSIVE STRENGTH (KSF)
SANDY SILTSTONE, (cont)		dark gray	low hardness		5-6-7-			1 2	1.5 1.5 1.5 2.5 2.5 1.0 .0 .0 .0	000
FREST THOMPSE ENDING			EXPLOR	L ATOF	RY BOI	-IN	IG LC	 G		-
Louncy-Raidveer Resociates									T1 -	
Foundation / Soil / Geological Engineers	-	PROJECT	ON CREE HALF MO	ON E	BAY, C	AL AL	FORN	NVES.	ΠGATI	NO
	-	349-2	110.	UP	1974		BORING			7

DRILL RIG Rotary Wash		SURFACE	ELEVATION	50	feet	7	LOGGE	D BY	R.D.F	
DEPTH TO GROUNDWATER 10.5 feet		BORING DI	AMETER (<u> incl</u>	nes		DATE D	RILLED		
DESCRIPTION AND CLAS	SIFI	CATION		- 		и.	ON CONTRACT ()	(35)		
DESCRIPTION AND REMARKS	SYM BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONFINED COMPRESSIVE STREHGTH (KSF)
Note: 120 feet of 2 inch diameter PVC piezometer pipe placed in boring and pea gravel placed around the sides of pipe. Dry Density = 117 pcf Percent Passing #200 Sieve = 41 Sand content decreasing at 138.0 feet		dark gray	low		- 121- - 122- - 123- - 124- - 125- - 126- - 127- - 128- - 130- - 131- - 132- - 131- - 132- - 135- 136- 137-		d. 3.		2.0 1.25 1.25 1.25 3.0 2.5 2.0 2.0 2.0 2.0 2.0	500
Note: The stratification lines represent the approximate boundary between soil types and the				-	138			15		
transition may be gradual. Bottom of Boring = 140.0 feet	\dashv			_	-140	+				
EQUITEU-FIREGUER RESOLUTES Foundation / Soil / Geological Engineers		DENNIS	STON CRE	EK C	ORY B	 DW	ATER	INVE	STIGA	TION
oon r deological Engineers		PROJ 349-	ECT NO.	ļ	DATE		ВОР	RING O.	1	

•

DRILL RIG Rotary Wash		SURFACE	ELEVATION	33	9 feet		.OGGE	DBY	R.D.R	•
DEPTH TO GROUNDWATER 2.5 feet		BORING D	IAMETER	6 inc	hes			RILLED	1/29/	
DESCRIPTION AND CLASS	SIFIC	CATION			DEPTH	LER	ATION 'ANCE S/FT.)	ER VT (%)	ling ff	FINED SSIVE IGTH
DESCRIPTION AND REMARKS	SYM BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONFINED COMPRESSIVE STRENGTH
SANDY SILT		dark brown- black	firm	ML	- 1 - - 2 - - 3 - - 4 - - 5 -		_∇_3	3/6/74	*	
SILTY SAND, fine grained		yellow- brown	medium dense	SM	- 6 - - 7 - - 8 -					ı
SAND, coarse grained with lense of red-brown silt, (decomposed granite sand)			medium dense	SP	- ? - - 10 - - 11 - - 12 -		28			
					- 13 - - 14 - - 15 - - 16 -					
CLAYEY SAND, coarse grained, with mica * Drilling rate faster than 1/4 min./ft. from 0 to 32 feet		i i	medium dense	SC .	- 17 - - 18 - - 19 - - 20 -					
LOWNEY-Noticeer (ISSOLINGS Foundation / Soil / Geological Engineers			ISTON CE HALE DJECT NO.	REEK MO	TORY I	1DW Y, (/ATER	RINV	ESTIG/	ATIO!

清洁

The state of the s

DRILL RIG Rotary Wash		·	ELEVATION	39 (cet		LOGGE		R.D.R	
DEPTH TO GROUNDWATER 2.5 feet		BORING E	DIAMETER	1 inch	es .		DATE D		1/29/	
DESCRIPTION AND CLAS	SSIFIC	ATION			DEPTH	SAMPLER	RATION TANCE (S/FT.)	WATER CONTENT (%)	Fr ::	CONCO
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAM	PEMETRATION RESISTANCE (BLOWS/FT.)	WA'	Drilling Rate min/ft	UNCONFINED
CLAYEY SAND (continued)		brown	medium dense	SC	 - 21 -					
					- 22 - - - 23 -					
					- 24 -					
					-25					
₽*				-	26 -					
					27 -					
					28 -					i
SILTY SAND, coarse grained, with mica, (decomposed granite sand)		orange- brown	very dense	SM- SP	-30		78			
Percent Passing #200 Sieve = 13				-	32	-	70			
				-	33				1.5	
				-	34 -				1.0	
				-	35 –				1.0	
				-	37 -				1.0	
SILTY CLAY, with trace of sand	b	1	•	CL+	88 -				1.0	
and trace of organic material	9	iray st	iff	CH - 3	9 -				0.30	
		1	EXPLC				ING I	OG		
teunsy-Kaldvear Resolutes		DENNIS	STON CRE	EK G	ROUNI	DW	ATER	INVE:	STIGA:	ΠC
Foundation / Soil / Geological Engineers			HALF ECT NO.	<u> MOO</u>	N BAY	, (BORI	DRNI) NG	Δ	
		349-	2	ιαΑ	il. 197	4	NO		2	

Page 1

.

DRILL RIG Rotary Wash			ELEVATION	37 1		_	LOGGE	DBY	R.D.R.	•
DEPTH TO GROUNDWATER 2.5 feet		BORING D	DIAMETER	4 incl	hes	<u> </u>	DATE		1/-	<u>;</u>
DESCRIPTION AND CLAS	-r			1	DEPTH	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	ing	FINED
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAM	PENET RESIS (BLOW	V/A CONTE	Drilling Rate min/ft	UNCONFINED
SILTY CLAY, (continued)		blue-	very	CL-	- 41 -		22		.30	
Percent Passing #200 Sieve = 69		gray	stiff	СН	├ <i>┼</i>		22	23		
reicent rassing "200 Steve - 67					42 -				1.0	
					- 43 -					
					- 44 -				.50	
SILTY SAND, fine grained				C. L	 45				.75	
TET 1 SATAD, The granica		gray	very dense	SM	- 46 -			}		
					- 47 -			.	.75	
				}	- 48 -			-	.75	ı
				F	49 -			-	.75	
				-	- 50-			-	.75	
				-	51 -		99			
,				L	52 -					
				-	53 -				0.5	
		-	·	E	54 -				0.5	
				-	-				0.3	
				-	55-				0.4	
				F	56				0.6	
				F	57 -				0.6	
					58 -).5	
					59 -					
					60-				0.5	
######################################			EXPLO	RAT	ORY BO)R	ING L	.OG		~
Lowney-Holdveer Associates		PENNIS	TON CRE	EK G	ROUND	W	ÁTER I	NVES	STIGAT	10
Foundation / Soil / Geological Engineers		PROJ	HALF M		DATE	<u>_A</u>	LIFOR		······································	
		349-2		A	pril, 19	74	- -i		2	

DRILL RIG Rotary Wash		SURFACE	ELEVATION	39 f€	et		LOGGE	D BY	R.D.R.	
DEPTH TO GROUNDWATER 2.5 feet		BORING D	HAMETER	4 inc	hes		DATE D	RILLED		7
DESCRIPTION AND CLAS			7	T	DEPTH	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	CONCLUENCE
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAS	PENE RESI (BLC	CCNT	Rair Bir	7755
SILTY SAND, fine grained		gray	very dense	SM	- 61 -					
					- 62 - 				0.25	
					- 63 -				0.25	
					- 64 - 65-				0.20	
·					- 66 -				0.40	
				-	67 -				0.5	
				- -	68 -				.75	
SANDY SILTSTONE, with shells,		gray-	low-		69 -			-	1.0	
fine grained sand (Purisima Formation)			hardness	-	- 70-	_	4/6"		1.0	
				E	71					
				-	72 -				1.3	
				-	73 -				.7	
				-	74 -				1.2	
Note: The stratification lines				-	75_			-	1.0	
represent the approximate boundary petween soil types and the				-	76 <u>-</u>				1.25	
ransition may be gradual.				-	77 - - 78 -				.75	
of Boring = 78.5 feet	=			=	79	110	0/6"			_
				-	30-					
Fisherman Farentes and so			EXPLO	RATO	DRY BO	DRI	NG L	OG		_
Lowney-Maldveer Associates		DENNIS	TON CRE	EK G	ROUNE 1 BAY	WA CA	ATER I	NVES	TIGATIO	_)
Foundation / Soil / Geological Engineers		PROJE	CT NO.		DATE		BORIN	VG		
		349-2		April	1974		NO.	. 2		

1

r.

DRILL RIG Rotary Wash		SURFACE	ELEVATION	50) feet	1	LOGGE	D BY	E.R.B.	and the second of the second o
DEPTH TO GROUNDWATER 1.3 feet		BORING D	DIAMETER	6 incl	nes		DATE D	RILLED		/74
DESCRIPTION AND CLAS	SIFIC	NOITA			DEPTH	E E	VION NVCE /FT.)	F. (°6.)	50 +	N.C. SIVE TH
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONFINED COMPRESSIVE STRENGTH (KSF)
CLAY		black- brown		CL	- 1 -			3/6/7 3/18/	4 74	
SILTY SAND, coarse grained, (decomposed granite sand)		brown- orange	medium dense	SM	- 2 3 4 -					=
(with clay pockets at 6.0 feet)		red- brown		(CL)	5 - 6 - 7		19			
			•	-	9 -		20			,
		·		 	12 -					
(with clay pocket at 16.0 feet)	5	gray c	lense ((CL) -	16 -	4	.			
				-	18 -					
•			EXPL	ORAT	ORY B	OR	ING	LOG	L	
Lowney-Haldveer Resociates		DENNIS	STON CR	EEK G)W	ATER	INVE:	STIGAT	ION
Foundation / Soil / Geological Engineers			ECT NO.		DATE		BOR	ING	3	
		349	-2	<u> </u>	1, 1974		N	0.	<u>ی</u>	

£.

DRILL RIG Rotary Wash		SURFACE	ELEVATION	5	0 feet		LOGGE	D BY	E.R.B.	•
DEPTH TO GROUNDWATER 1.3 feet		BORING D	NAMETER	6 inc	hes		DATE C	RILLED	2/27/	74
DESCRIPTION AND CLASS	IFIC.	ATION	7	~ _} ~~~~	DEPTH	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	FINED
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAM	PENET RESIS (BLOW	CONTE	Ret	UNCONFINED
SILTY SAND, (continued)		gray	dense	SM	- 21 -		45			
	l					_ـــــــــــــــــــــــــــــــــــــ	1 43			
	.				- 22 - 					
					- 23 - 					
					- 24 -					
			very dense		25	Т				
·					- 26 -		98			
					- - 27 -			-		
					- 28 -		.			
					- 29 -					
			•							
					- 30 		51			
					- 31 -	Ц		}		
				}	32 -			-		
					33			.		
		-		-	. , 34 -			-		
		·	,	F	- 35	\mathbb{H}		-		
	- 9	gray			36 -		32	17		
SANDY CLAY	1		very	CL	37	1				
				L	38					
				F	+					
			,	F	39 -					
					40 —					-
Misserge-Markelsanson Managaine.					ORY E					-
Lownzy-Naidveer Associates		DENNI	STON CR HALF	EEK (GROUN IN BAY	DW	/ATER	INVE	STIGA	TIC
Foundation / Soil / Geological Engineers		PRO	JECT NO.		DATE			RING	7	
		349-	.2	Ар	ril, 197	4			3	

DRILL RIG Rotary Wash		SURFACE	ELEVATION	50	feet		LOGGE	DBY	E.R.B.	
DEPTH TO GROUNDWATER 1.3 feet		BORING D	IAMETER	6 in	ches		DATE D			-
DESCRIPTION AND CLAS	SIFIC	NOITA				8.	TION FT.)	(3°)	2 +	-
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETPATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (°C)	Drilling Rate min/ft	THE CASE OFFICE
SAND, coarse-medium grained, with clay lenses		blue- gray	very dense	SP- SM	- 41 - - 41 -		66			
(clay lense at 43.5 to 44.5 feet)					- 42 - 43 - 44 - 45					
			·		46 - 47 - 48 - 49 -				,	
				- - - -	50 51 - 52 -		52			
					53 - 54 - 55-					
,				-	56 – 57 –					
LTY SAND, coarse – medium grained, with clay lenses		rown- ve range de	ery S ense	5M- - :	58 - 59 - 50-					
Lowney-Haldveer Associates			EXPLO	RATC	PRY B	ORI	ING L	OG		_
Foundation / Soil / Geological Engineers		DENNIS. PROJE	TON CREE HALF M CTNO.	02013	ROUNIE BAY, date	W.C.A	ATER II LIFOR BORIN	NIA	TIGATI	(

DRILL RIG Rotary Wash	—— -		ELEVATION	50 f			LOGGE		E.R.B.
DEPTH TO GROUNDWATER 1.3 feet		BORING DI	AMETER	6 incl	nes	L_	DATE D		
DESCRIPTION AND CLASS	SIFIC	ATION .	r	1	DEPTH	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAM	PENET RESIS	CONT	Drilling Rate min/ft
SILTY SAND, (continued)		brown- orange	very dense		- 61 - - 62 -		50/4	ı	
					63 - - 64 -				
					65 66 -				
		٠.			- 67 - - 68 -				
SAND, medium to fine grained, uniform		gray- brown	very dense	SP	- 69 - 70- 	1	50/4'		
					- 71 - - 72 - 	1 ,			-
					- 73 - - 74 - - 75-				
SANDY SILTSTONE, fine grained		gray-	low		 - 76 - 				
sand, with shells (Purisima Formation)		blue	hardness		- <i>77</i> - - 78 -				
					- 79 - 80		50/2''	_	
Lowney-Neldveer Associates	ā	DEV 12			TORY				
Foundation / Soil / Geological Engineers					on ba	Υ,			
. canadian / con / declogical Engineers		 	0JECT NO. 349-2		April,			ORING NO.	3

			SURFACE ELEVATION 50 feet				- T	LOGGED BY FRR			
	DRILL RIG Rotary Wash						\dashv		E.R.B.		
	DEPTH TO GROUNDWATER 1.3 feet		BORING DIAMETER 6 inch			nes T	닖.	DATE DRILLED		2/27/74	
	DESCRIPTION AND CLAS	ATION			DEPTH	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate : min/ft sconfineD		
	DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAN	PENE RESI (BLO)	W, CONT	Drillin Rote min/ft	
	SANDY SILTSTONE, (continued)		gray- blue	low hardne	ss ss	_ 81 _ _ 81 _					
		£178°		, ,		- 82 - - 83 -				=	
						- 84 -					
			•		,	85 - 86 -				1.15	
						- 87 - - 87 -			,	1.20	
		-				- 88 - - 89 -			π	1.20	
				4		 - 90- - · -	1				
	(with shells, cemented siltstone at 91.5 to 92.5 feet)	`			į	- 91 - - 92 -		÷	18		
	Percent Passing #200 Sieve = 29 Dry Density = 112 pcf		-	·	,	- 93 - 93		·		45 sec/ft	
						- 94 - 95-			- - -	1.05 sec/	
					-	96 -			-		
	Note: The stratification lines represent the approximate boundary between soil types and the		•	,		97 -			- -		
	transition may be gradual.				-	- 99 - - 100 =					
+	Bottom of Boring = 100.0 feet										
	2		EXPLORATORY BORING LOG								
	Lowney-Maidveer Associates	DENN	DENNISTON CREEK GROUNDWATER INVESTIGAT HALF MOON BAY, CALIFORNIA								
	Foundation / Soil / Geological Engineers		PROJECT NO. DATE BORING NO.				3				

養養

DRILL RIG Rotary Wash			ELEVATION		feet	LOGGEDBY R.D.R			
DEPTH TO GROUNDWATER 2.3 feet		BORING D	IAMETER	4 in	ches	DATE DRILLI	ED 1/3		
DESCRIPTION AND CLAS	SSIFIC	CATION			050-1	TION NCE (FT.)			
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	PENETRATION RESISTANCE (BLOWS/FT.) WATER	Drilling Rate		
SANDY SILT		dark brown	stiff .	ML	- 2 3	_∇_ 3/6/	774		
CLAYEY SAND, with fine gravel		brown	loose	SC -	- 4	_ □ 3/18/	74		
					9 -	9	,		
					12 - 13 - 14 -				
			•		16 - 17 - 18 -				
CLAYEY SAND, with gravel	Ъr	1	edium S nse	\	19 -				
			EXPLO	RATO	DRY BOI	RING LOG			
Lawney-Haldveer Associates		DEVIKUC.				······································			
Foundation / Soil / Geological Engineers		PROJE	<u> </u>	MOC	ROUNDV DN BAY, DATE	VATER INVE	IIA .		
	- 1	349-2	· ·	Apri	1, 1974	NO.	4		

14 4

DRILL RIG Rotary Wash		SURFACE	ELEVATION	70 f	ect		LOGGE	R.D.R	
DEPTH TO GROUNDWATER 2.3 feet		BORING DI	AMETER	6 ir	nches		DATE D	RILLED	
DESCRIPTION AND CLAS	SSIFIC	CATION			DEPTH	ER	ATICN ANCE 3/FT.)	ER IT (°3.)	
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATICH RESISTANCE (BLOWS/FT.)	WATER CONTENT (%3)	Drilling Rate min/ft
CLAYEY SAND, (continued)		brown	mediur dense	SC	 - 21 -		21		
					- 22 -				
					- - 23 -				
					 - 24 -				
					- 25-				
			·		- 26 -				
					- 27 -				
				-					ı
				-	- 28 -			.	
				-	- 29 -			-	
clay content decreasing at 30 feet		c	dense		30-	Н			
				-	31		49	-	
				F	32			-	
,				-	33				
					34 -				
			•	-	4				
					35				
				-	36 –				
			,	-	37 -			-	
				F	38			-	
				-	39 -				
				L	40				
						1			
Lownsy-listaveer Associates			EXPLO						
Foundation / Soil / Geological Engineers		PENNIS	STON CRI HALF		GROUN ON BA'				
Telephonical Engineers			ECT NO.		DATE		BOR	ING	
		349-	2	<u> </u>	April,	197	'4 N	O. 4	4

DRILL RIG Rotary Wash		SURFACE I	ELEVATION	70 f		_	LOGGE	!	R.D.R.	
DESCRIPTION AND CLAS	SIFIC		MACIEN	TITC	1163		DATE D			
DESCRIPTION AND REMARKS	SYM- BOL	1	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONFINED
CLAYEY SAND, (continued)		brown	dense	SC	- 41 - 41		80			
					- 42 - - 43 -					1
					- 44 45					
					- 46 - - 46 -			-		
	٠				- 47 - - 48 -					
SILTY SAND		· · · · · · · · · · · · · · · · · · ·	very dense	SM	- 49 - - 50-					
				- - -	51 -					
					53 - 54 -					
				-	55					
				-	56 -					
				-	58 - 59 -					
·					60					-
Lowney-Malducer Nasociates			EXPLO	DRAT	ORY E	30	RING	LOG		
Foundation / Soil / Geological Engineers			ECT NO.	MOC	ROUN DN BAY DATE	<u> </u>	CALIE (STIGA [.] A 4	TI

10 Kg

DRILL RIG Rotary Wash DEPTH TO GROUNDWATER 2.3 fee			ELEVATION	<u> 70 re</u>		\perp	LOGGED BY R.D.R				
		BORING DI	AMETER	6 incl	nes	\perp	DATE D	RILLED	1/30		
DESCRIPTION AND CLA	SSIFIC	NOITAC				α	TION NCE FT.)	(3)	Υ		
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (*	Drilling Rate min/ft		
SILTY SAND, (continued)		blue- gray	very dense	SM	 - 61 -		71				
	п				- - 62 -	-					
				-							
				F	- 63 -			ŀ			
					64 -			-			
				-	- 65-			-			
				F	66 -			L			
			1	E	67						
				F	4						
				E	68 –			-			
				+	69 -			<u> </u>			
				L	70				1		
				+	_, -	7	6				
				1.	71 -		0				
					72 _			-			
					73 –			-			
				- 7	74						
				F.,	,_						
				F	5-						
				上7	6 -						
,				- 7	7 -						
				F 78	3						
				F	4						
·				79]				_		
				80				-	_		
Forms 11 and			EXPLOR	ATOF	RY BO	BIN	1G 1 O	<u> </u> G			
Lownzy-Kalduser Resociates	一	ENNISTO									

undation / Soil / Geological Engineers

I		ALLIN DAY, CA	LLEORNIA		
1	PROJECT NO.	DATE			
1	240.0	D/(IL	BORING	1	
1	349-2	A	NO.	4	
_;		April, 1974	140.		

DRILL RIG Rotary Wash			ELEVATION		cet		LOGGE	DBY	R.D.R	}	
DEPTH TO GROUNDWATER 2.3 feet		BORING DI	IAMETER (6 inch	es		DATE DRILLED 1/30/				
DESCRIPTION AND CL/	ASSIFIC	CATION			DEPTH	ER	ATION ANGE I/FT.)	ER (°)	Bu →	T	
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETPATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft		
SILTY SAND, (continued) silt content decreasing with depth		brown	very dense	- 9	81 - 82 - 83 - 83 - 84 - 85 - 86 - 87 - 88 - 90 - 91 - 92 - 93 - 94 - 95 - 96 - 97 - 98 - 99 - 90 - 90 - 90 - 90 - 90 - 90	83	94				
Lawney-Haidveer Asseriates		DENNIS.	EXPLO		·····						
Foundation / Soil / Geological Engineers		PROJE	TON CRE HALF A	MOOL	ROUNI 1 BAY, DATE	۷۷ <i>,</i> ۲	ALIFO BORII	RNIA		-	
		349-2		۸.,	ril, 19	71	NO		4		

DRILL RIG Rotary Wash		SURFACE	ELEVATION	70	feet	T	LOGGE	D BY	R.D.F	}
DEPTH TO GROUNDWATER 2.3 feet		BORING D	IAMETER 6	inch	es		DATE D	RILLED		
DESCRIPTION AND CLAS	SIFIC	CATION			DEPTH	LER	IAT!ON ANCE S/FT.)	ER 4T (%)	Drilling Rate min/ft	CALVE SSLVE GTH
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Dri Rati	UNCOFFINEL COMPRESSIVI STRUNGTH
SILTY SAND, (continued)		brown	very dense	SM- SP	-102 - -103 - 					
CLAY STONE, with shells (Purisima Formation)		dark blue	low hardness		-104 - -105 - -106 - -107 - -108 - -109 -			-		r
Bottom of Boring = 110.3 feet					111 - 112 - 113 - 114 - 115 - 1					
Note: The stratification lines represent the approximate boundary petween soil types and the transition may be gradual.				- - - - - - -	116 -					
COUNCY-LESSONER GESCHIELS Foundation / Soil / Geological Engineers			ston cre	EEK C	GRY BO GROUND DN BAY	 DW	'ATER	inve drni.	STIGA	ΠΟΝ

皇 城

de la companya de la

T

A STATE OF THE STA

DRILL RIG Rotary Wash		SURFACE	ELEVATION	6	4 feet	Loc	LOGGED BY E.R.B.				
DEPTH TO GROUNDWATER 2 feet at tim	e of	BORING D	IAMETER	6 inc	ches	DAT	E DRILLE	0 2/21	/74		
drillin DESCRIPTION AND CLAS	ia				DEPTH	ATION	S/FT.) ER (T (%)	- Bu	SSIVE STH GTH		
DESCRIPTION AND REMARKS	SYM BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER PENETRATION RESISTANCE	(BLOWS/FT.) WATER CONTENT (%)	Prilling Rate min/ft	UNCONFINED COMPRESSIVE STRENGTH		
CLAY		black	CL	CL	- 1 -		3/18	74			
SAND, coarse grained		brown	loose	SP	2 -	7_	z at tir drilli	ne of ing			
		:			- 4 - - 5 - 5 -	6					
ORGANIC SILT, with roots and wood fragments		black	soft	OL	- 6 - - 7 - - 8 -				,		
Dry Doneity - 63 not					9 - - 9 - - 10 -		89				
Dry Density = 63 pcf					- 11 - - 12 -	2	69				
Sand lense at 14.5 feet					- 13 - - 14 -						
SILTY CLAY, with gravel			medium stiff	CL	- 15 - 16 -	7	27				
•					- 17 - - 18 -						
					- 19 - - 20				·		
-	L		FXPI	ORA	TORY B	ORIN	IG I O	G G			
Lowncy-Neidveer Associates		DENN	iston cr	REEK		DWAT	ER INV	/ESTIGA	JICh		
Foundation / Soil / Geological Engineers		PRO	DJECT NO.	1	DATE	, <u>J</u>	BORING	*17.1			
		349	-2		April, 19	74	NO.	5			

*

į

DRILL RIG Rotary Wash			ELEVATION	64 1	cet		LOGGE	E.R	. F	
DEPTH TO GROUNDWATER 2 feet at tir		BORING D	IAMETER	6 incl	nes		DATE D	RILLED	^/21 <i>/</i>	_ /7
DESCRIPTION AND CLA	•	NOITA			DEPTH	ER	TICN NOE /FT.)	R F (°5)		- 1
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%3)	Drilling Rate min/ft	
SILTY SAND, fine grained		dark gray	medium dense	SM	- 21 - - 21 - - 22 - - 23 -		24			+
COARSE SAND, with gravel		blue- gray	dense	SP -	24 - 25 - 26 - 26 -		46/5			
				- - - - -	27 - 28 - 29					
-				- - - - - -	31 - 32 - 33 -		98			
GRANITE, decomposed, little fractured	a	lack m	od. hard		34 - 35- 36 -				4	
Bottom of Boring = 36.0 feet lote: The stratification lines present the approximate boundary tween soil types and the ansition may be gradual.					37 - 38 - 39 - 40 - 40 - 40 - 40 - 40 - 40 - 40 - 4					
LEWNSY-INFOURT RESULTSES		DENNIS. H PROJE	EXPLO TON CREE ALF MOC	EK GI DN BA	ROUND)W	ATFR II	VVES.	TICA TI	- (

搜查

灣家

DRILL RIG Rotary Wash		SURFACE	ELEVATION	Ī	24 feet		LOGGE	D BY	E.R.	B.
DEPTH TO GROUNDWATER 0.0 feet		BORING D	IAMETER	6 i	nche s		DATE D	RILLED	2/21/	
DESCRIPTION AND CLAS	SSIFIC	CATION			DEDT	Æ		}	1	
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONTINED
CLAYEY SILT		black	soft	ML	- , -			3/5/ 3/18/	74 74	\dagger
CLAYEY SAND		brown	loose	SC	- 2 -					4
					- 3 -				: 	
SANDY CLAY		black	soft	SC	- 4 -	\times				
. *			·		- 5 -					
		blue- gray			7 -		·	-		,
COARSE SAND, with gravel,		gray-	very	SP -	8 -					
(decomposed granite sand)		black	dense	3r -	- 10-					
					, 11		0/6"			
				- -	12 -					
		-		-	14					
Percent Passing #200 Sieve = 6		ight rown			15	 88	5/6"			
					16 + 1					
				-	18 -					
				-	19					
					20	96,	/6" 2	7		
Lawney-Naiduear Resociates			EXPLO							
Foundation / Soil / Geological Engineers			TON CRE HALF M	1001	BAY.	CA	ATER I	nves	TIGAT	1C
		349-2			DATE 11, 197	4	BORII		6	

沙土

Ü.

DRILL RIG Rotary Wash		SURFACE	ELEVATION	124 f	eet	T	LOGGE	D BY	R.D.	P
DEPTH TO GROUNDWATER 0.0 feet		BORING D	DIAMETER	6 inc			DATE D	RILLED		
DESCRIPTION AND CLAS	SSIFIC	ATION				α.	TON VCE FT.)	, § ?	T	
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONFINES COMPHESSIVE STRENGTH
SANDY CLAY, coarse grained granite sand		blue- black	very	CL	- 21 22 23 25 27		108/3"			
Percent Passing #200 Sieve = 39 Grading harder decomposed bedrock at 35 feet				-	31 - 32 - 33 - 34 -					·
Bottom of Boring = 35.0 Note: The stratification lines represent the approximate boundary between soil types and the transition may be gradual.					36 - 37 - 38 - 39 - 40-					
LOWNEY-NEIGUEER RESECTIFIES Foundation / Soil / Geological Engineers			EXPLO STON CRE HALF M	EK G .00h	ORY BOUND BAY, DATE	OW, CA	ATER I	NVES NIA ING	STIGAT	101

建花

1

W.

DRILL RIG Rotary Wash		SURFACE	ELEVATION	62	Feet	L	OGGE	D BY	R.D.R
DEPTH TO GROUNDWATER 0.0 feet		BORING D	IAMETER 6	inch	es	D	ATE D	RILLED	
DESCRIPTION AND CLAS	SIFIC	CATION			DEPTH	LER	ATION ANCE S/FT.)	ER .T (%)	· To
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	✓ WATER CONTENT (%)	Drilling Rate min/ft
CLAY		black		CL	- 1 -			3/6/ 3/18/	
SILTY SAND, coarse, (decomposed granite sand)		Ve	lense	SM-	- 2	3.	4		
Lownsy-linidueer Associates				RAT	ORY BO				
		PENNIS	TON CRE	EK G	ROUND	WA	TER I	NVES	TIGATI
Foundation / Soil / Geological Engineers		PROJE	HALF M	<u> </u>	DATE	_AL	IF UK	IVIA	

PROJECT NO.

349-1

DATE

April, 1974

BORING

NO.

7

DRILL RIG Rotary Wash		SURFACE	ELEVATION	62 1	feet	T	LOGGE	D RY		
DEPTH TO GROUNDWATER 0.0 feet		BORING D	IAMETER	6 inc		+	DATE D		E.R. 2/22	
DESCRIPTION AND CLAS	SIFIC	ATION				æ	TION NCE FT.)	(%)		T
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONFINED COMPRESSIVE
SILTY SAND, (continued)		brown	dense	SM	21		31			3
CLAYEY SAND, coarse gravel		blue- gray	dense	SC	- 22 - - 23 -					
·					- 24 - - 24 - - 25 - - 26 -		36	-		
SILTY SAND, medium grained, some clay fines	- 1	olue- gray	dense	SM	28 -		54			,
AND, coarse grained, with gravel	b		ery :	SP _	31 -		14			
rading fine at 35.0 feet, uniform		ue-			35 - 36	79				
Percent Passing #200 Sieve = 10			s	-3	87 - 8 - 9 -					
				M 4	ORY BO	ים	NC 1	000		_
Lowney-Kaldveer Asseriates		DENNIS	TON CRE						TIO 4 =	
Foundation / Soil / Geological Engineers			HALF /	MOOI	V BAY,	C.A	LIFO	rnia	HGAT	10)
		PROJE	UINO.		, 1974		BORIN NO		7	

養養

A.

13

		·								
DRILL RIG Rotary Wash			ELEVATION	62	feet		LOGGE	D BY	R.D.R	
DEPTH TO GROUNDWATER 0.0 feet		BORING D	IAMETER 6	inche	S		DATE D	RILLED	2/22/	74
DESCRIPTION AND CLAS	SIFIC	CATION			DEPTH	EB	TION NOCE /FT.)			
DESCRIPTION AND REMARKS	SYM BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETPATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UMCONFINED COMPRESSIVE STRENGTH
SAND, (Continued)		blue- gray	very dense	SP- SM	- 41 - - 42 -		78			·
•					43 - 44 - 45 - 46 -		72			
SAND, fine grained			·	L_	47 - 48 - 49 -					,
JAND, Time grained			Very dense	- - -	50 51 52	8	33			
					54 -					
				- 5 - 5 - 5	7 - 8 -					
				- 59 - -60	-	90				
Lownsy-Haldveer Associates		DENNIST	EXPLO	EK GR	OUND	W.A	ATFR I	NVF5	TIGATI	7
Foundation / Soil / Geological Engineers		PROJECT 349-2	CT NO.	1001	BAY, OATE	CA —	JFOR BORIN NO.	NIA ig	······································	-

DRILL RIG Rotary Wash		SURFACE E	ELEVATION	62	feet	_	LOGGE		R.D.R.	
DEPTH TO GROUNDWATER 0.0 feet		BORING DI	AMETER	δi	nches				2/22/	74
DESCRIPTION AND CLAS	SIFIC	CATION)	γ	DEPTH	SAMPLER	PENETRATION RESISTANCE (BLOW/S/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONTINED COMPAGESSIVE STRENGTH
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	§ V§	PENE RESI (BLO)	W, CONT		COMP. STRI
SAND, (continued)		blue	very dense	SP	- 61 -		90			
SANDY SILTSTONE, with shells, deeply weathered		gray- blue	low hardness		62				0.5	
(Purisima Formation)					- 63 - 64 -				2.15	
Percent Passing #200 Sieve = 45 Dry Density = 123 pcf					65			13	1.55	
Bottom of Boring = 66.0 feet					- 66 - - 67 -					
					68 -					ē
					- 69 - 70					
					71 -					
Note: The stratification lines					- 72 - - 73 -					
represent the approximate boundary between soil types and the transition may be gradual.					74					
					75 					
					- 76 - - 77 -					
					78					
					- 79 - - 80-					
)	<u> </u>	<u> </u>	FXPI	LOR	ATORY	В	ORING	a LO	G G	
Lewney-Heldveer Associate	5	DENIN	uiston c							ATIC
Foundation / Soil / Geological Engineers	:	PF		MC	ON BA DATE	Y,	CALIF		IA	

· ·

The state of the s										
DRILL RIG Rotary Wash		SURFACE	ELEVATION	55	feet		LOGGE		E.R.B	
DEPTH TO GROUNDWATER 1.5 feet		BORING D	IAMETER	6 i	nches		DATE D	RILLED	2/25/7	
DESCRIPTION AND CLAS	SIFIC	CATION			DEPTH	1	ATION ANCE S/FT.)			INCD SSIVE
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	1	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	COMPRESSIVE STRENGTH
CLAY		black		CL	- 1 - - 1 - - 2 -			3/6/7	4	
CLAYEY SAND, coarse with lenses of sandy clay and clean sand			medium dense	SC	- 3		13			
SAND, coarse grained			edium (-	16 - 17 - 18 - 19 -		13			
Lowngy-Kaldveer (Issatiates Foundation / Soil / Geological Engineers			EXPLC TON CRE HALF M ECT NO.	ek g oon	ROUNE	OWA CAI	ATER I	NVES NIA ng		02

DRILL RIG Rotary Wash		SURFACE	ELEVATION	E E	£	T.			
DEPTH TO GROUNDWATER 1.5 fee	t	BORING D			<u>feet</u> nches		-OGGE		E.R.B.
DESCRIPTION AND CL					inches	1	ATE D	RILLED	2/25/74
		Ţ		·	DEPTH	LER	SATION TANCE S/FT.)	ER 4T (°5;	ing Sive
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (°5;	Drilling Rate min/ft UNCONFINE
SAND, (continued)		red- brown	medium dense	SP	- 21	IT	46	0	- 59
grading silty at 25.0 feet				SP	22 - 23 - 24 - 25 - 26 -	4.	5		
SANDY CLAY, coarse grained sand lenses	1 1		ery (-	60			
				- 36 - 37 - 38 - 39 - 40-					
Lowney-Raldveer Resociates	DFN		XPLORA	TOR'					
Foundation / Soil / Geological Engineers		PROJECT I	N CREEK ALF MOC	GROL <u>N BA</u> dat	1. CAI	-100	INV RNIA RING	ESTIG 4	ATION

DRILL RIG Rotary Wash		SURFACE	ELEVATION	55	feet		LOGGE	D BY ·	R.D.R.	
DEPTH TO GROUNDWATER 1.5 fcet		BORING D	DIAMETER	6 inc	hes			RILLED	2/25/74	
DESCRIPTION AND CLAS	SSIFIC	CATION			DEPTH	ER	ATION ANCE (/FT.)	ER T (%)	5 0 20 20 20 20 20 20 20 20 20 20 20 20 20	SIVE
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rote min/ft	COLIPPECSSIVE
SAND, medium to fine grained		blue- gray	very	SP-SM-	- 41		92			
			EVD 6		60		26			_
Lowncy-Heldveer Associates					ORY B					
		DENNI	Ston cre Half M	EK G	ROUN	DW.	ATER	INVE	STIGATIO	Ο.
Foundation / Soil / Geological Engineers		PRO	JECT NO.		DATE	∪A L	1			
		349-	·········	Apr	il, 197	4	BOR	IING O.	8	

騆

**

X.

30 m

DRILL RIG Rotary Wash		SURFACE	ELEVATION	55	feet		LOGGE	D BY	R.D.R.	
DEPTH TO GROUNDWATER 1.5 feet		BORING DI	IAMETER	6 incl	nes		DATE D			<u> </u>
DESCRIPTION AND CLASS	SIFIC	ATION				H.	TION NCE /FT.)	er [1	====
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CCNTERIT (%)	Drilling Rate min/ft	COLIFICACINE
SAND, (continued)		brown	very dense	SP- SM	61 -		96			
		blue- gray			- 63 - - 64 - - 65 - - 66 - - 67 - - 68 -					
grading silty at 70.0 feet				(SM)	- 69 - - 70 - - 71 - - 72 - - 73 - - 74 -		81		1.15	
SANDY SILTSTONE, weakly cemented, little fractured, a few shells (Purisima Formation)		-,	ow lardness		75 - 76 - 77 - 78 - 79 -	56	5/4"		1.15	
Lowney-ligitueer fissoriates Foundation / Soil / Geological Engineers			TON CRE HALF JECT NO.	EK G MOC	ROUNE NO BAY DATE pril, 19	OF WA	ATER ALIFO	INVE:	STIG/TI	<u> </u>

A.

A Company

\$\$ \$ \$

DRILL RIG Rotary Wash		SURFACE	ELEVATION	55 f	eet	T	LOGGE	D BY	E.R	D
DEPTH TO GROUNDWATER 1.5 feet		BORING DI	AMETER 6	inch	es.		DATE D	RILLEC	2/25/	
DESCRIPTION AND CLAS	SIFIC	ATION				æ	TION NCE FT.)	T		1.0
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONFINED
SANDY SILTSTONE, (continued)		gray- black	low hardness		81 - 82 - 83 - 84 - 85 - 86 - 87				1.15	
		·	-		88 -		50/2"		` `	
Bottom of Boring = 91.0 feet ote: The stratification lines epresent the approximate boundary etween soil types and the ansition may be gradual.				- - - - -	92 - 93 - 94 - 95 - 96 - 97 - 98 - 99 -					
LEWNSY-HELICURAL RESOLUTES Foundation / Soil / Geological Engineers	[ENNIST	EXPLO CON CREE HALF M	· · · · · · · · · · · · · · · · · · ·		<u> </u>	ATER I	nives Rnia	TIGAT	!C
	;	349-2		Anri	1, 197	1	BORI		,	

DESCRIPTION AND CLASSIFICATION DESCRIPTION AND REMARKS SYM COLOR CONSIST. SOIL FEET STANDING PROJECT NO. DESCRIPTION AND REMARKS SYM COLOR CONSIST. SOIL FEET STANDING PROJECT NO. DESCRIPTION AND REMARKS SYM COLOR CONSIST. SOIL FEET STANDING PROJECT NO. DESCRIPTION AND REMARKS SYM COLOR CONSIST. SOIL FEET STANDING PROJECT NO. DESCRIPTION AND REMARKS SYM COLOR CONSIST. SOIL FEET STANDING PROJECT NO. DEPTH STANDING	DRILL RIG Rotary Wash		SURFACE	ELEVATION	36	feet		.OGGE	D BY	R.D.R	•
SANDY CLAY, coarse grained sand, grading to clayey sand orange-stiff brown CLAYEY SAND, coarse grained orange-medium brown orange-medium brown orange-medium brown orange-medium brown dense 11	DEPTH TO GROUNDWATER 1.5 feet		BORING DI	IAMETER 6	inch	ie s			RILLED	<u>~/2.5</u>	/74
SANDY CLAY, coarse grained sand, grading to clayey sand orange-stiff brown length of the brown length of	DESCRIPTION AND CLA	SSIFIC	ATION	·	 _	DEPTH	PLER	RATION TANCE VS/FT.)	TER ENT (%)	lling e	E SSIVE
town dense Lown dense Lown dense Exploration / Suit / Geological Engineers brown dense Exploratory Boring Log Exploratory Sociation (Sociation)	DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE		SAM	PENET RESIS (BLOV	CONTE	Pat min	UNCOULTRE!
Lewingy-Kalduger Reputates Exploratory Boring Log Exploratory Boring Log Exploratory Boring Log Exploratory Boring Log HALF MOON BAY, CALIFORNIA	sand, grading to clayey sand			stiff	CL	- 3 - - 4 - - 5 - - 6 - - 7 - - 8 -			3/6/7		
Lewisy-Raidveer Associates DENNISTON CREEK GROUNDWATER INVESTIGA HALF MOON BAY, CALIFORNIA	CLAYEY SAND, coarse grained		brown	dense		- 11	3	37			
Foundation / Soil / Geological Engineers PENNISTON CREEK GROUNDWATER INVESTIGA HALF MOON BAY, CALIFORNIA	Lownou-Holdveer Associates	i									
DDO 1507 110		•	DENNI	STON CR HALF	WO:	GROUN On BAy	DW /, C	ATER ALIF	inve Orni	ESTIGA <u>A</u>	TIC
349-2 April, 1974 NO. 9	2200giodi Engineers					DATE		ВО	RING		

. .

(x)

重

2

DRILL RIG Rotary Wash		SURFACE	ELEVATION	36 fe	et		LOGGE		F.R
DEPTH TO GROUNDWATER 1.5 feet		BORING D	IAMETER	6 in	ches		DATE D	RILLEC	2/2
DESCRIPTION AND CLA	ASSIFIC	CATION	-		DEPTH	1	TION INCE /FT.)		
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate
CLAYEY SAND, (continued)		orange- brown	medium dense	SC	_ 21 _		40		
			401.50		_ 22 _	I			
					- - 23 -				
					- 24				·
SILTY SAND		orange brown	very dense	SM	25 -	\prod	56		
				<u> </u>	27 -	4			
					28 -				
SAND, coarse grained		gray	dense	SP	29 -			-	
				- - -	31 -		32		
				-	32 -				
					33 -				
silty sand lense at 35.0 feet		·		-	35				
grading fine grained below 35.0				-	36 -	4	10		
				F	37 – 38 –				
				-	39 -				
					10-				\dashv
Lewney-Raldynar Granisas			EXPLO	RATO	RY BO	ORI	NG L	OG	

Lounzy-Raldveer Resoliates

Foundation / Soil / Geological Engineers

DENNISTON CREEK GROUNDWATER INVESTIGATION HALF MOON BAY, CALIFORNIA

PROJECT NO. DATE BORING
349-2 April 1974 NO. o

DRILL RIG Rotary Wash		SURFACE	ELEVATION	36 fc	eef		LOGGE	DBY	- · ·	
DEPTH TO GROUNDWATER 1.5 feet		BORING D	DIAMETER	6 inc		1			2/25/	<u>D.R.</u>
DESCRIPTION AND CLAS	SSIFIC	CATION					SAC		~	
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST,	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (°s)	Drilling Rate min/ft	COMPRESSIVE
SAND		gray	dense	SP	- 41 -					- 0
			very dense		- 42 - - 43 - - 44 - - 45 - - 46 - 47 -		62	-		
					48 - 49 - 50- 51 - 52 -					,
					53 - 54 - 55 - 56 - 57 - 57 - 57 - 57 - 57 - 57	8	7			
				-	8 -					
Lowney-Kaldveer Associates		ENINUCT	EXPLOF							
Foundation / Soil / Geological Engineers	Ĺ	PROJEC	ON CREE HALF MO	JON	OUND\ BAY, (νΑ [Α]	TER IN	VIA	IGATI	0:
		349-2	2		1974		NO.	ы 9		

1.

DRILL RIG Rotary Wash		SURFACE	ELEVATION		fect		LOGGE	D BY	R.D.	<u>.</u> К.
DEPTH TO GROUNDWATER 1.5 feet	<u> </u>	BORING D	IAMETER (6 incl	nes		DATE D	RILLED	2/25	77
DESCRIPTION AND CLAS	SIFIC	ATION		T	DEPTH	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONFINED
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAN	PENET RESIL	CCNI	Dril Rate mio,	0000
SAND, (continued)		blue- gray	very dense	SP	- 61 - - 62 -					
					- 63 - - 64 - - 65	-				
SANDY SILTSTONE, with shells, fine grained sand (Purisima Formation)		dark gray	low hardness		- 66 - 67 - 7		50/6"		1.3	
	·		•		- 68 - - 69 - - 70-				1.2	
					71 - 72 - 73 -				1.3	
					74 - - 74 - - 75 - - 76 -		·		1.0	
Note: The stratification lines represent the approximate boundary petween soil types and the transition may be gradual.					- 77 - - 77 - 78 -				1.5	
Percent Passing #200 Sieve = 39				-	79 -		50/2"		1.5	
Bottom of Boring = 80.5 '	=				- 80	ΠÏ)U/ Z'}_	-		
Lowney-Kaidveer Resociates Foundation / Soil / Geological Engineers		DENN	iston cr	REEK	GROUN	1D,	WATER	NVI	ESTIGA	- .Т
. ounouton / Son / Geological Engineer s		PRC 349	DJECT NO. -2	A	DATE pril, 19	74		RING NO.	9	

秦治

DRILL RIG Rotary Wash		SURFACE	ELEVATION	27	feet	LO	GGED BY F.D.
DEPTH TO GROUNDWATER 3.5 feet		BORING D	IAMETER (5 inch	ies		TE DRILLED 2/2
DESCRIPTION AND CLAS	SSIFIC	CATION				~ S	
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER PENETRATION	RESISTANCE (BLOWS/FT.) A WATER CONTENT ("0.) Drilling Rate
SANDY CLAY, with coarse granitic sand		black	firm	CL	- 1 - - 2 -		376/:4
		brown			- 3 - - 4 - - 5 -	_	∇ 3/18/74
			stiff		7 -	14	
sand content increasing with depth					9 - 10 - 11 - 12 - 13 - 14 -	16	
ILTY SAND, minor amount of clay	b		ry S	M	15 - 16 - 17 - 17 - 17 - 17 - 17 - 17 - 17	52	
·				- 1	8 - 9 - 0 -		
Lounge-Haldwoor Georgia			EXPLO	RATO	RY BO	RINC	LOG
Lowney-Haldveer Resociates Foundation / Soil / Geological Engineers			HALF M	OON	BAY, (VATE	r investiga: Ornia
	ŀ	PROJEC 349-2	JI NO.		, 1974	B	ORING NO.

建设

张士)

DRILL RIG Rotary Wash		SURFACE I	ELEVATION	27 fc	et		LOGGE		E.R.B.
DEPTH TO GROUNDWATER 3.5 feet		BORING DI	IAMETER 6	inch	es I I	<u> </u>			2/23/
DESCRIPTION AND CLASS	SIFIC	ATION	~		DEPTH	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	ing ft
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAM	PENET RESIS (BLOV	CONTE	Drilling Rate min/ft
SILTY SAND, (continued)		brown	dense	SM	- 21 -		40		
					22 -	!			
no clay below 25.0 feet					- 24 - - 25 -		00		
fine uniform sand		blue- gray	very dense	SM	- 26 - - 27 -		90		,
					- 28 - - 29 -				
·					-30 - - 31 -		98		
			·	` . }	32 -				
					- 34 - - 35		·		
				-	36		59		
					37 -				
				- - - -	39 -			•	
			EXPL	ORA	TORY I	30	RING	LOG	 ì

Lowney-Kaldveer Associates

Foundation / Soil / Geological Engineers

DENNISTON CREEK GROUNDWATER INVESTIGA HALF MOON BAY, CALIFORNIA

PROJECT NO.	DATE	BORING	
349-2	April, 1974	NO.	10

				·						
DRILL RIG Rotary Wash		SURFACE	ELEVATION		feet	_	LOGGE	DBY	R.D.R	
DEPTH TO GROUNDWATER 3.5 feet		BORING D	IAMETER (3 inch	es		DATE D		2/23/	/7/
DESCRIPTION AND CLAS	SIFIC	ATION			DEPTH	EB	ATION ANCE	ER T (°3)	60	NED
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (°3)	Drilling Rote min/ft	UNCOMPINED
SILTY SAND, (continued)		blue- gray	verý dense	SM	41		92			
					- 42 - - 43 -					
			'		- 44 -					
					45	Π	98			
		İ			- 46 - - 47 -					
				 - -	48 -					
					- 49 - - 50		96			
				- - -	51 -					
				- - -	52 -					
				-	54 -			-		
					- 55— - - - - - -					•
SILTY SANIDSTONIE I II					57 -					
SILTY SANDSTONE, with shells (Purisima Formation)	1		low hardness	F	58 -			1	/3	
					60	_53	3/1"			
Gunnu-Valduaa- G			EXPLO	DRAT	ORY B	OF	RING	LOG		
Lowney-Haldveer Resolutes Foundation / Soil / Geological Engineers				EEK (N BAY,	DV C	VATER ALIF C	INVE RNIA	ESTIGA \	TI
		34	JECT NO.	 	DATE oril, 19		ВОР	IING O.		

DRILL RIG Rotary Wash		SURFACE	ELEVATION	27	feet		LOGGE	D BY	R.D	R.
DEPTH TO GROUNDWATER 3.5	feet	BORING D	DIAMETER	6 inc	hes			RILLED	2/22/7	<u>i</u>
DESCRIPTION A	ND CLASSIFIC	CATION	CATION		DEDTU		TION NCE (FT.)	(5)		VED SIVE
DESCRIPTION AND REMARK	SYM BOL	COLOR	CONSIST.	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCONFINED COMPRESSIVE STRENGTH
SILTY SANDSTONE, (cont	inued)	blue- black	low hardness		 - 61 -					
Dry Density = 113 pcf		J. Tuek	Haranes		- 62 -			15		
Bottom of Boring = 63.0 fee	et				- 63 - - 64 -	111				
·					- 65					
					- 66 -					
				,	68 -			- - -	ı	
·			-	-	69 -			- -		
Note: The stratification lines represent the approximate both between soil types and the transition may be gradual.	undary			- - - - - -	- 70 - 71 - - 72 -					
				- - - -	73 - 74 - 75 -					
				-	76 - 77 - 78 -					
,					79 - 80-					
			EXPLO	RAT	ORY B	OR	ING I	OG		
Lowney-Haldveer Asso		DENNI:	STON CRE	EK G	ROUN	DW.	ATER	INVE:	STIGAT	101
Foundation / Soil / Geological En	Foundation / Soil / Geological Engineers			HALF MOON BAY, CALIFORNIA PROJECT NO. DATE BORING						
				Apr	il, 197	4	NO		10	

DRILL RIG Rotary Wash		SURFACE I	ELEVATION	145	feet	LOGG	EDBY	R.D.R.
DEPTH TO GROUNDWATER Not established	d	BORING DI	AMETER &	inch	es		DRILLED	2/21/
DESCRIPTION AND CLASS	SIFIC	NOITA			DEPTH	ER VTION VNCE	18. 16.5	59
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER PENETRATION RESISTANCE	WATER CONTENT (*.	Drilling Rate min/ft
SANDY SILT, with organic material SILTY SAND, coarse grained granitic sand with trace of clay	BUL	black orange- brown	soft	ML	- 1	3	0	
			dense		- 13 - - 14 - - 15 - - 16 - - 17 - - 18 - - 19 - - 20 -	34		
Lowney-Kaldveer Assaciates Foundation / Soil / Geological Engineers	<u> </u>	PRO	ston cr	EEK (GROUN OON BADDATE	DWATE	r inv	ESTIGA

繼麗


4.1

Datary Wash	7	SUBEACE	ELEVATION	1547	· ·	7			
DRILL RIG ROTCHY Wash		IAMETER 6		feet		LOGGE		R.D.R.	
DEPTH TO GROUNDWATER Not established				inche	es	\perp	DATE D		2/21/74
DESCRIPTION AND CLAS	SIFIC	ATION	γ	γ	DEPTH	LER	PATIO TANCE S/FT	TER NT (°,	gui di Cilvi.
DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST.	SOIL TYPE	(FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (*.)	Drilling Rate min/ft
SILTY SAND, (continued)		orange- brown	medium dense	SM	- 21 -		6		
					- 22 - - 23 -				
SAND, coarse grained		blue grey	medium dense	SP	- 24 - - 24 - - 25 -				
grading finer with depth				- - -	26 -		14		
		<u> </u>		-	28 -			,	
CLAYEY SAND		blue	medium dense	SC -	31 -		23		
		·			33 -				
				F	35		29		
					37 - 38 - 39 - 40				
	-		EXPLO	RATO	RY B	J OR	ING L	OG	
Lowney-Haldveer Resociates Foundation / Soil / Geological Engineers			ON CREE HALF M	k gr oon	OUND BAY,	WA	TER.IN	1VEST	TIGATIO
		949-2			DATE 1, 1974	4	BORIN NO.		11

张起

7

	DRILL RIG Rotary Wash		SURFACE	ELEVATION	145	foot	T	LOGGE	D BY	0.0.0	
	DEPTH TO GROUNDWATER Not established	BORING D	IAMETER	6 inc					R.D.R: 2/21/	74	
	DESCRIPTION AND CLAS	SIFIC	CATION			5555	E				d C
	DESCRIPTION AND REMARKS	SYM- BOL	COLOR	CONSIST	SOIL TYPE	DEPTH (FEET)	SAMPLER	PENETRATION RESISTANCE (BLOWS/FT.)	WATER CONTENT (%)	Drilling Rate min/ft	UNCCNE
	CLAYEY SAND, (continued)		blue	Very dense	SC	- 41 - - 42 -		50/6"	***************************************		
	GRANITE, highly weathered and decomposed		gray– blue	low hardnes	- ·	- 43 - - 44 - - 45 - - 46 - - 47 -					
						48 - 49 - 50 - 51 - 52 - 53 - 54 -				2	
	moderately weathered, little fractured				- - -	55				4	
re be tro	ote: The stratification lines present the approximate boundary etween soil types and the consition may be gradual. ottom of Boring = 61.0				F	57 - 58 - 59 -					
							<u> </u>				
	Lowney-Haldveer Associates Foundation / Soil / Geological Engineers	DENINIST PROJE 349		ek g ogn	ROUNI	OW, CAL	ATFR I	NVES		10	




Louney-Raidveer Recentles

Foundation / Soil / Geological Engineers

PUMPING TEST - (DRAWDOWN VS. TIME)

DEMNISTON CREEK GROUNDWATER INVESTIGATION
H'ALF MOON BAY, CALIFORNIA

PROJECT NO.	DATE		
349-2	April, 1974	FIGURE	A-2



ELAPSED TIME AFTER TERMINATION OF PUMPING

Lowney-Maldveer Associates

Foundation / Soil / Geological Engineers

PUMPING TEST - (RECOVERY VS. TIME)

DENNISTON CREEK GROUNDWATER INVESTIG, HALF MOON BAY, CALIFORNIA

PROJECT NO.	DATE	FIGURE	
349-2	April, 1974	TIOONE	A-3

APPENDIX B - LABORATORY TESTING

The laboratory testing program was directed towards a quantitative and qualitative evaluation of the physical and mechanical properties of the soils underlying the site.

Natural water content was determined on seven samples of the materials recovered from the borings. The water contents are recorded on the boring logs at the appropriate sample depths.

Dry density determinations were performed on 21 samples to measure the unit weight of the subsurface soils. Results of these tests are shown on the boring logs at the appropriate sample depths.


The percent soil fraction passing the No. 200 Sieve was determined on 10 samples of the subsurface soils to aid in the classification of the soils. Results of these tests are shown on the boring logs at the appropriate sample depths.

Gradation tests were performed on 6 samples of the subsurface soils. These tests were performed to assist in the classification and to determine grain size distribution of the soils. Results of these tests are presented on Figures B-1 and B-2.

UNIFIED SOIL CLASSIFICATION SYSTEM

(ASTM D 422.72)





COBBLES	GRA	VEL		SAND		
COBBLES	COARSE	FINE	COARSE	MEDIUM	FINE	SILT AND CLAY


KEY SYMBOL	BORING NO.	SAMPLE DEPTH (feet)	ELEV. (feet)	UNIFIED SOIL CLASSIFICATION SYMBOL	SAMPLE DESCRIPTION
	1	20.5	*** **** ****	SM	Brown Silty Sand with Gravel
	1	41.0		CL	Gray Sandy Clay
	1	63.0		SM	Blue-Gray Silty Sand
				,	

•	GRADATION TEST DATA				
Lownsy-Kaldveer Associates	DENNISTON CREEK GROUNDWATER INVESTIGATIO				
Foundation / Soil / Geological Engineers	HALF" MOON BAY, CALIFORNIA				
	PROJECT NO.	DATE	. ,		
	349-2	March, 1974	Figure B-1		

UNIFIED SOIL CLASSIFICATION SYSTEM

(ASTM D 422-72)





COBBLES	GRA	GRAVEL		SAND			
	COARSE	FINE	COARSE	MEDIUM	FINE	SILT AND CLAY	

KEY	BORING NO.	SAMPLE DEPTH (feet)	ELEV. (feet)	UNIFIED SOIL CLASSIFICATION SYMBOL	SAMPLE DESCRIPTION
	5	30.0		SP	Brown-Gray Sand with Gravel
	8	50.0		SM	Brown Silty Sand
	9	45.0		SP	Blue-Gray Sand

Lownsy-Holdveer Associates Foundation / Soil / Geological Engineers	GRADATION TEST DATA			
	DENNISTON CREEK GROUNDWATER INVESTIGATION HALF MOON BAY, CALIFORNIA			
	PROJECT NO.	DATE		
	349-2	March, 1974	Figure B-2	

APPENDIX C

EXPLANATION OF HYDROLOGIC INVENTORY FACTORS

A brief explanation of how quantities of water used in the hydrologic inventory were estimated is as follows:

Items of Inflow

Streamflow, or runoff from the watershed areas was taken as 80 percent of the total watershed precipitation (12,000 acre feet) for Denniston Creek as estimated by the U.C. Agricultural Extension Service.

Precipitation, over the lowland area of the basin is calculated as the average annual precipitation of 20 inches over an area of 879 acres.

Subsurface Inflow, from consolidated rock is assumed to be negligible, since probably little transmittable water is stored in the granitic rocks or in the siltstone of the Purisima Formation.

Subsurface Inflow, from San Vicente Subarea is estimated from the relationship Q = TIL, where Q equals the quantity of subsurface flow, T is the coefficient of transmissibility, I is the hydraulic gradient, and L is the width through which the subsurface flow is occurring. The critical width is taken as 0.3 mile, other hydraulic properties as noted in preceding sections of this report.

Items of Outflow

Streamflow, to Half Moon Bay was considered to be that quantity remaining after 20 percent of inflow is recharged to the basin by seepage losses.

Consumptive Use, by evaporation and phreatophytes is calculated as the product of the acreage occupied by this vegetation (approximately 650 acres) and a consumptive use factor of 2 acre feet per acre per year. This factor may be somewhat low, but accounts for the prevalence of coastal fog in reducing the amount of evaporation and consumptive use.

Pumpage for Irrigated acreage is taken as an applied water use factor of 2 acre feet per acre over an irrigated acreage determined from recent aerial photographs to be about 500 acres, mostly in the Denniston Creek Subarea.

Subsurface Outflow, to the Bay is estimated from the same relationship used for Subsurface Inflow, above. The critical cross-section width is taken at 1 mile.

Surface Water Export, to the Coastside County Water District's water treatment plant is based on data supplied by the District; other pumpage data obtained from Department of Water Resources estimates.